

1




Fig. 1




Fig. 2




Fig. 3

10020054-131301

10020064-121301




Fig. 4




Fig. 5

10020064-121301




Fig. 6

10020064-121301

Initial Gloss Value before Laponite B Treatment




FIG. 7

Specular Gloss Change After Coating with Laponite B
 (-ve value is loss in gloss)




FIG. 8




FIG. 9

10020054-19002007